

Printed by EAST

UserID: ARodriguez

Computer: WS11348

Date: 05/02/2001

Time: 14:35

Type	L #	Hits	Search Text	DBS	Time Stamp	Comments	Error Definition	Errors
1	BRS	11	351 micro adj actuator	USPAT; EPO; JPO; Derwen	2001/05/02 10:29			0
2	BRS	L6	4 1 and reflector	USPAT; EPO; JPO; Derwen	2001/05/02 09:37			0
3	BRS	L11	1 1 and diffraction adj grating and laser	USPAT; EPO; JPO; Derwen	2001/05/02 09:41			0
4	IS&R	L16	0 ("310/40").CCLS.	USPAT; EPO; JPO; Derwen	2001/05/02 09:41			0
5	IS&R	L21	777 ("310/40mm").CCLS.	USPAT; EPO; JPO; Derwen	2001/05/02 09:41			0
6	BRS	L26	30 21 and laser	USPAT; EPO; JPO; Derwen	2001/05/02 09:41			0

Type	L #	Hits	Search Text	DBS	Time Stamp	Comments	Error Definition	Errors
7	BRS	L31	0	26 and transmitter	USPAT; EPO; JPO; Derwen	2001/05/02 09:42		0
8	BRS	L36	4	21 and transmitter	USPAT; EPO; JPO; Derwen	2001/05/02 09:43		0
9	BRS	L41	6	21 and micro adj actuator	USPAT; EPO; JPO; Derwen	2001/05/02 09:44		0
10	BRS	L46	3	41 and laser	USPAT; EPO; JPO; Derwen	2001/05/02 09:45		0
11	BRS	L51	1	1 and diffraction adj grating and laser	USPAT; EPO; JPO; Derwen	2001/05/02 10:33		0
12	BRS	L56	30	1 and micro adj machines	USPAT; EPO; JPO; Derwen	2001/05/02 10:37	Truncation Overflow. Return string from Server is: 5`88676`1	1

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Err ors
13	BRS	L61	4	1 and optical adj communication	USPAT; EPO; JPO; Derwen t	2001/05/02 10:40		0
14	BRS	L66	13	1 and wavelength	USPAT; EPO; JPO; Derwen t	2001/05/02 10:44		0
15	BRS	L71	28	1 and mems	USPAT; EPO; JPO; Derwen t	2001/05/02 10:47		0
16	BRS	L76	50	1 and rotation	USPAT; EPO; JPO; Derwen t	2001/05/02 10:48		0
17	BRS	L81	1	76 and reflector	USPAT; EPO; JPO; Derwen t	2001/05/02 10:49		0
18	BRS	L86	5	76 and wavelength	USPAT; EPO; JPO; Derwen t	2001/05/02 10:50		0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
19	BRS	L91	12	76 and laser	USPAT; EPO; JPO; Derwen t	2001/05/02 10:56		0
20	IS&R	L96	116	("318/436").CCLS.	USPAT; EPO; JPO; Derwen t	2001/05/02 10:56		0
21	BRS	L101	1	96 and actuator and micron	USPAT; EPO; JPO; Derwen t	2001/05/02 10:56		0
22	BRS	L106	8	96 and actuator	USPAT; EPO; JPO; Derwen t	2001/05/02 10:57		0
23	BRS	L111	53	mechanical adj actuator and micron	USPAT; EPO; JPO; Derwen t	2001/05/02 10:58		0
24	BRS	L116	21	111 and laser	USPAT; EPO; JPO; Derwen t	2001/05/02 10:59		0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Err ors
25	BRS	L121	14	111 and laser and rotat\$	USPAT; EPO; JPO; Derwen	2001/05/02 11:01	Truncation Overflow. Return string from Server is: 5`167938`	1
26	BRS	L126	9	121 and wavelength	USPAT; EPO; JPO; Derwen	2001/05/02 12:10		0
27	IS&R	L131	935	("372/99").CCLS.	USPAT; EPO; JPO; Derwen	2001/05/02 11:15		0
28	BRS	L136	1	131 and rotat\$ and micron and actuator	USPAT; EPO; JPO; Derwen	2001/05/02 11:19	Truncation Overflow. Return string from Server is: 5`0`0`ROT	1
29	BRS	L141	823	372/102	USPAT; EPO; JPO; Derwen	2001/05/02 11:20		0
30	IS&R	L146	532	("372/102").CCLS.	USPAT; EPO; JPO; Derwen	2001/05/02 11:20		0

Type	L #	Hits	Search Text	DBs	Time stamp	Comments	Error Definition	Errors
31	BRS	L151	4	146 and rotat\$ and micron and actuator	USPAT; EPO; JPO; Derwen	2001/05/02 11:36	Truncation Overflow. Return string from Server is: 5`0`0`ROT	1
32	IS&R	L156	382	("372/23").CCLS.	USPAT; EPO; JPO; Derwen	2001/05/02 11:36		0
33	BRS	L161	0	156 and actuator and micro	USPAT; EPO; JPO; Derwen	2001/05/02 11:36		0
34	BRS	L166	4	156 and actuator and rotat\$	USPAT; EPO; JPO; Derwen	2001/05/02 11:38	Truncation Overflow. Return string from Server is: 5`93921`2	1
35	IS&R	L171	3	("5771252").PN.	USPAT; EPO; JPO; Derwen	2001/05/02 12:10		0
36	BRS	L176	0	171 and fabry adj perot	USPAT; EPO; JPO; Derwen	2001/05/02 12:16		0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
37	BRS	L181	140 mems and wavelength	USPAT; EPO; JPO; Derwen t	2001/05/02 12:16			0
38	BRS	L186	64 181 and rotat\$	USPAT; EPO; JPO; Derwen t	2001/05/02 12:17		Truncation Overflow. Return string from Server is: 5`0`0`ROT	1
39	BRS	L191	43 186 and laser	USPAT; EPO; JPO; Derwen t	2001/05/02 12:26			0
40	BRS	L196	894 mems	USPAT; EPO; JPO; Derwen t	2001/05/02 12:27			0
41	BRS	L201	3 196 and 372/\$9.ccls.	USPAT; EPO; JPO; Derwen t	2001/05/02 12:29			0
42	BRS	L206	1 micro adj actuator and 372/\$9.ccls.	USPAT; EPO; JPO; Derwen t	2001/05/02 12:30			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
43	BRS	L211	81 micro adj actuator and piezoelectric	USPAT; EPO; JPO; Derwen	2001/05/02 12:35			0
44	BRS	L221	0 211 and 372/\$9.cc1s.	USPAT; EPO; JPO; Derwen	2001/05/02 12:35			0
45	BRS	L216	15 211 and laser	USPAT; EPO; JPO; Derwen	2001/05/02 12:56			0
46	IS&R	L226	3 ("5771252").PN.	USPAT; EPO; JPO; Derwen	2001/05/02 12:56			0
47	BRS	L231	0 226 and wavelength and mode adj hops	USPAT; EPO; JPO; Derwen	2001/05/02 12:58	Truncation Overflow. Return string from Server is: 5`66968`1	1	
48	BRS	L236	1 226 and wavelength and mode	USPAT; EPO; JPO; Derwen	2001/05/02 13:07			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
49	BRS	L241	4	micro adj machined adj actuator	USPAT; EPO; JPO; Derwen t	2001/05/02 13:40'		0
50	BRS	L246	99	fabry adj perot and diffraction adj grating and wavelength and transmitter	USPAT; EPO; JPO; Derwen t	2001/05/02 13:41		0
51	BRS	L251	0	246 and "1550nm"	USPAT; EPO; JPO; Derwen t	2001/05/02 13:42		0
52	BRS	L256	70	246 and nm	USPAT; EPO; JPO; Derwen t	2001/05/02 13:46		0
53	BRS	L261	32	256 and 372/.ccls.	USPAT; EPO; JPO; Derwen t	2001/05/02 13:43		0
54	BRS	L266	9	246 and "1550" adj nm	USPAT; EPO; JPO; Derwen t	2001/05/02 13:54		0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Err ors
55	BRS	L271	22 tunable adj laser and fabry adj perot and "1550" adj nm	USPAT; EPO; JPO; Derwen	2001/05/02 14:06	.	.	0
56	BRS	L276	13 271 and 372/\$.ccls.	USPAT; EPO; JPO; Derwen	2001/05/02 13:57	.	.	0
57	BRS	L281	2 tunable adj laser and fabry adj perot adj laser and "1550" adj nm	USPAT; EPO; JPO; Derwen	2001/05/02 14:06	.	.	0